




KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

KARPAGA VINAYAGA
MEDICINE
DENTISTRY
ENGINEERING
NURSING
EDUCATIONAL GROUP

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES



MAINTENANCE LOG

Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

GENERAL MAINTENANCE

Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

MAINTENANCE LOG

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
1.	2/01/20	oral Pathology	Water is leaking from the roof in staffs room	2/01/20	water leaking is fixed.	
2.	2/01/20	Oral & Maxillofacial Surgery	light is not working, in Minor OT.	4/01/20	light is repaired.	
3.	3/01/20	Prosthodontics	electric short circuit. in Sterilisation Room	3/01/20	Wiring is done.	
4.	3/01/20	Public Health dentistry	Main Door is not closing	7/01/20	door is fixed.	

Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
5)	6/01/20	Pedodontics	FAN IS NOT WORKING IN X-RAY ROOM	6/01/20	fan is fixed in the X-ray room -	
6.	4/01/20	Orthodontics	Window is not closing in the left side	7/01/20	window is closed and fixed	
7.	4/01/20	Periodontics	Fan is not working in PG clinic.	7/01/20	fan is fixed in PG clinic.	
8	6/1					

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
1.	6/01/20	oral medicine opd Radiology	Floor tiles are Broken	8/01/20	Tiles is fixed	
2.	7/01/20	Orthodontics	light is not working here OP	8/01/20	Light is Fixed.	
3.	7/01/20	Conservative Dentistry	Window glass is broken	9/01/20	Window glass are fixed	
4.	8/01/20	Public Health Dentistry	Cupboard door is not closing properly.	10/01/20	Cupboard is fixed	
5.	8/01/20	Periodontics	light is not working in chair room OP	8/01/20	light is fixed	



Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
6	9/01/20	Pedodontics	Fan is not working	10/1/20	Fan is fixed.	[Signature]
7	9/01/20	Periodontics	water is leaking in the floor	9/01/20	Water leaking is fixed	[Signature]
8	10/1/20	Endodontics and Conservative	Front door is not closing	11/1/20	Door is fixed	[Signature]
9	11/1/20	OMFS	Fan is not working in minor OT	13/1/20	Fan is working properly.	[Signature]
10	11/1/20	ORAL MEDICINE	Window door is not closing properly.	13/1/20	Window door is fixed.	[Signature]

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

BIOMEDICAL MAINTENANCE

Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

MAINTENANCE LOG

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
1.)	2/01/20	Periodontics	Dental chair light is not working in OP chair	2/01/20	dental chair light is fixed.	
2.)	2/01/20	Oral and maxillofacial surgery	Dental chair position not working in minor OP chair	3/01/20	Dental chair Position problem fixed.	
3.)	3/01/20	OMR	Suction is not working in the chair	4/01/20	suction is working properly.	
4.)	4/01/20	PH D	Scale is not working	4/01/20	scaling is fixed.	

Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam (tk), Tamilnadu 603 308

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
57	4/01/20	conservative and Endodontics	Three way syringe is not working in of chair	4/01/20	Three way syringe is fixed.	
67	4/01/20	Public Health Oncology	light is not working properly	4/01/20	light is fixed.	

Dean

KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
1.)	6/01/20	Prosthodontics	Dental chair suction is not working	6/01/20	suction is fixed	Pooli.
2.)	7/01/20	orthodontics	Three way syringe is not working	7/01/20	Three way syringe is not working	
3.)	7/01/20	OMFS	Pressure is not working	7/01/20	Pressure is working	
4.)	8/01/20	oral medicine and radiology	Fixed and Swoloper solution is not changed	8/01/20	fixer and swoloper is changed	
5.)	9/01/20	Periodontics.	Scalae is not working.	9/01/20	Scalae fixed	dh

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES

GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
6.	9/01/20	Proetho	Three way syringe is not working	9/01/20	Three way syringe fixed	
7.)	10/01/20	oral pathology	Specimens taking dental chair is position not working	10/01/20	Dental chair is in working condition	
8.)	11/01/20	ortho	chair position in not working	11/01/20	chair position is working condition	

S

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.