LOG BOOK OF MAINTENANCE COMMITTEE



Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.

S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
71	20.9.21	DMR	window is not closing properly	21.9.21	window is repaired	
72	23.9.21	Periodontics	Light is not working.	24.9.21	Light is working.	
73	24.9.21	Endodontics	Fan not working	25.9.21	Fan changed	
74	28.9.21	PHD	Fan speed is slow.	28.9.21.	Condenser is changed.	
75	29.9.21	OMFS	Switch board is broken.	30.9.21.	Switch board is changed.	

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
76	4.10.21	PHD	Light is not Working.	5.10.21	New light is changed.	
77	5.10.21.	OMR	Water Leakage	5.10.21.	Tap is fixed	
78	8.10.21.	Endodontics	Light is not working	8.10.21	Light is working.	
79	12.10.21	Prosthodontics	Water leakage	12.10.21	Tap is fixed	
80	15.10.21	pedodontics	Light not working	15.10.21	light changed	

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.

KARPAGA VINAYAGA
INSTITUTE OF DENTAL SCIENCES
GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308



Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.

KARPAGA VINAYAGA
INSTITUTE OF DENTAL SCIENCES
GST Road, Chinna Kolambakkam, Padalam (po), Chengalpattu (dt)
Madhuranthagam(tk), Tamilnadu 603 308



S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
101	16-12-21	Perio.	chair light is not working.	16-12-21	chair light is working.	
102	20/12/21	OMFS	Needle burner not working	22/12/21	Needle burner working.	
103	28/12/21	ONR.	Fan not working	28/12/21	Fan repaired	
104	29/12/21	PHD	chair suction is not working.	30/12/21	chair suction is working.	
105	30/12/21	Oral pathology	chair Position is not working	30/12/21	chair position is working.	

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.



S.NO	DATE	DEPT	ISSUE	DATE	MAINTENANCE WORK DONE	SIGN
106	3/1/22	Perio	Suction not working	3/1/22	Suction Working	
107	4/1/22	Ortho	Chair light not Working	4/1/22	Working	
108	7.1.22	Endo	Aizotor not working.	7.1.22	Working	
109	7.1.22	OMFS	Suction Leaking.	7.1.22	Leak fixed.	
110	10.1.22	OMR	Developer & fixer is not changed	11.1.22	Developer & fixer is changed	

Dean
KARPAGA VINAYAGA INSTITUTE OF DENTAL SCIENCES
G.S.T. Road, Chinna Kolambakkam,
Palayanoor Post, Madhuranthagam Taluk,
Chengalpattu District-603 308.